## **WINDOWS / FIREPLACES / ATTIC**

Interior Windows/Glass								
General condition:	✓ Satisfactory	☐ Marginal	□ Poor	☐ Painted shut				
☐ Hardware missing	☐ Glazing compound		ked glass ☐ E	Broken counter-balance mech.				
☐ Surface deterioration: (See Remarks page) ☐ Representative number of windows operated								
Evidence of leaking insulated glass: ☐ Yes ☐ No ☐ Not determinable ☑ N/A								
Safety glazing:	✓ N/A □ Sa	fety issue	Where:					
Security bars present:	✓ Yes □ No	•	☐ Test release n	nechanism before moving in				
Fireplace ☐ None Location(s): Family room								
☐ Gas ✓ Wood ☐ Woodburner stove (See Remarks page)								
☐ Masonry insert	✓ Metal insert	☐ Metal	□ Electric					
☐ Blower built-in		es 🗆 No	☑ Damper operates ☐ Damper missing					
☐ Open joints or cracks in f	1		☐ Pre-fabricated panels damaged/worn					
Hearth: Satisfactory:	✓ Yes □ No		Mantle: ✓ NA ☐ Loose					
✓ Recommend having flue cleaned and re-examined								
Stairs	<b>☑</b> Sa	tisfactory	☐ Marginal	□ Poor □ None				
Handrail:	✓ Satisfactory	☐ Marginal	□ Poor	☐ Safety Hazard				
Risers/Treads:	✓ Satisfactory	☐ Marginal	□ Poor	☐ Risers/treads uneven				
Smoke/CO Detectors (See Remarks page)								
Smoke detector:  Yes	•		☐ Not tested	CO detector: ✓ Yes ☐ No				
Attic								
Access:	s <b>V</b> Pulldown	☐ Scuttlehole	☐ Knee wall	□ No access				
		the attic	☐ Other	_ 1 (0 1100000				
Location: $\square$ Bedroom hall $\square$ Bedroom closet $\square$ Garage $\square$ Other								
Flooring:								
Insulation: Type: Fibergla	•		Average inches:	6-9				
Installed		☐ Rafters	□ Walls	☐ Not Visible				
Vent fans: ✓ Not Present ☐ Not tested ☐ Thermostat controlled ☐ Safety Hazard								
Ventilation: ✓ Appears adequate ☐ Recommend additional venting								
Roof structure:								
✓ Trusses □ Other □ Not visible								
Roof sheathing: ✓ Plyw	vood □ OSB	☐ 1x wood	☐ Other					
□ Rotte	ed	☐ Delaminated	Satisfactory	☐ Marginal ☐ Poor				
Fans exhausted to: Attic	e: 🗹 Yes 🗆 No	Outside:	☐ Yes ☑ No	$\square$ Not visible $\square$ N/A				
(See Remarks page)								
Chimney chase: ☐ Satis	3	eds repairs	✓ Not visible					
Structural problems observed: ☐ Yes ☑ No ☐ See comments below								
Vapor barriers: ✓ Not v		properly installed						
☐ Kraf		`	emarks page)					
Electrical:	n junction box(es)	☐ Handyman wi	iring	☐ Visible knob-and-tube				
General Comments								
1. Flue is not part of this inspection due to limitations on visual inspection, recommend ask for								
last professional chimney report and continue to have chimney and unit inspected / cleaned as								
needed.  Trusses showed no major defects or demage at the time of inspection								
<ol> <li>Trusses showed no major defects or damage at the time of inspection.</li> <li>Roof sheathing, examined from the attic, showed no major defects or moisture damage.</li> </ol>								
4. Insulation was average, but could be upgraded.								
<b>→.</b> 1115u16	mon was average, but t	ourd of apgraded.		5. Ventilation was average, but could be appraised.				